



SHIPBOARD EXPOSURE TESTING OF AIRCRAFT MATERIALS ABOARD USS RANGER

E. Tankins, J. Kozol, E. Lee
Air Vehicle and Crew Systems Technology Department (Code 6063)
NAVAL AIR WARFARE CENTER
AIRCRAFT DIVISION, WARMINSTER
P.O. Box 5152
Warminster, PA 18974-0591

2 MAY 1994

FINAL REPORT

19970604 093

Approved for Public Release; Distribution is unlimited

DEED QUALITY INSPECTED 3

Prepared for
NAVAL EXPLORATORY DEVELOPMENT PROGRAM
AIRCRAFT MATERIAL BLOCK, MA2A

U9500006

NOTICES

REPORT NUMBERING SYSTEM — The numbering of technical project reports issued by the Naval Air Warfare Center, Aircraft Division, Warminster is arranged for specific identification purposes. Each number consists of the Center acronym, the calendar year in which the number was assigned, the sequence number of the report within the specific calendar year, and the official 2-digit correspondence code of the Functional Department responsible for the report. For example: Report No. NAWCADWAR-92001-60 indicates the first Center report for the year 1992 and prepared by the Air Vehicle and Crew Systems Technology Department. The numerical codes are as follows:

CODE	OFFICE OR DEPARTMENT
00	Commanding Officer, NAWCADWAR
01	Technical Director, NAWCADWAR
05	Computer Department
10	AntiSubmarine Warfare Systems Department
20	Tactical Air Systems Department
30	Warfare Systems Analysis Department
50	Mission Avionics Technology Department
60	Air Vehicle & Crew Systems Technology Department
70	Systems & Software Technology Department
80	Engineering Support Group
90	Test & Evaluation Group


PRODUCT ENDORSEMENT — The discussion or instructions concerning commercial products herein do not constitute an endorsement by the Government nor do they convey or imply the license or right to use such products.

Reviewed By: J. Waldman Date: 12/8/94
Branch Head

Reviewed By: J. S. Shuff Date: 12/9/94
Division Head

Reviewed By: A. H. Hume Date: 12/9/94
Director/Deputy Director

DISCLAIMER NOTICE



THIS DOCUMENT IS BEST QUALITY AVAILABLE. THE COPY FURNISHED TO DTIC CONTAINED A SIGNIFICANT NUMBER OF COLOR PAGES WHICH DO NOT REPRODUCE LEGIBLY ON BLACK AND WHITE MICROFICHE.

REPORT DOCUMENTATION PAGE

Form Approved
OMB No. 0704-0188

Public reporting burden for this collection of information is estimated to average 1 hour per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to Washington Headquarters Services, Directorate for Information Operations and Reports, 1215 Jefferson Davis Highway, Suite 1204, Arlington, VA 22202-4302, and to the Office of Management and Budget, Paperwork Reduction Project (0704-0188), Washington, DC 20503.

1. AGENCY USE ONLY (Leave blank)		2. REPORT DATE 2 MAY 1994	3. REPORT TYPE AND DATES COVERED FINAL	
4. TITLE AND SUBTITLE SHIPBOARD EXPOSURE TESTING OF AIRCRAFT MATERIALS ABOARD USS RANGER			5. FUNDING NUMBERS	
6. AUTHOR(S) E. TANKINS, J. KOZOL, E. LEE				
7. PERFORMING ORGANIZATION NAME(S) AND ADDRESS(ES) Air Vehicle and Crew Systems Technology Department (Code 6063) NAVAL AIR WARFARE CENTER; AIRCRAFT DIVISION, WARMINSTER P.O. Box 5152 Warminster, PA 18974-0591			8. PERFORMING ORGANIZATION REPORT NUMBER NAWCADWAR-94019-60	
9. SPONSORING / MONITORING AGENCY NAME(S) AND ADDRESS(ES) NAVAL EXPLORATORY DEVELOPMENT PROGRAM AIRCRAFT MATERIALS BLOCK, NA2A			10. SPONSORING / MONITORING AGENCY REPORT NUMBER	
11. SUPPLEMENTARY NOTES				
12a. DISTRIBUTION / AVAILABILITY STATEMENT APPROVED FOR PUBLIC RELEASE; DISTRIBUTION IS UNLIMITED.			12b. DISTRIBUTION CODE	
13. ABSTRACT (Maximum 200 words) <p>This report describes the results of 4 months of exposure to the Naval Environment of an aircraft carrier flight deck on a variety of aircraft materials and coatings. Test specimens included aluminum-lithium alloys, metal matrix composites, laminates and primerless paint.</p>				
14. SUBJECT TERMS ALUMINUM ALLOY, SHIPBOARD EXPOSURE TESTING, CADMIUM PLATED STEEL			15. NUMBER OF PAGES	
			16. PRICE CODE	
17. SECURITY CLASSIFICATION OF REPORT UNCLASSIFIED	18. SECURITY CLASSIFICATION OF THIS PAGE UNCLASSIFIED	19. SECURITY CLASSIFICATION OF ABSTRACT UNCLASSIFIED	20. LIMITATION OF ABSTRACT SAR	

Shipboard Exposure Testing of Aircraft Materials Aboard USS Ranger (Jan-May 1991)

Introduction

A variety of aircraft materials and finishes are being exposed in the naval environment of aircraft carrier decks to provide information for the development of realistic and accelerated corrosion testing. In addition, the corrosion behavior of materials intended for application on present and future naval aircraft is being determined.

This report describes the effects of 4 months of exposure on a variety of aircraft materials and coatings aboard the USS Ranger during deployment to the Western Pacific and the Persian Gulf. The overall exposure aboard the Ranger was abbreviated, compared to the usual deployment. As a result, the aluminum control specimens and most of the other specimens sustained minimal corrosion. The magnesium alloys included in this exposure test experienced significant corrosion effects and are discussed in a separate report (Ref. 1).

Exposure ConditionsExposure Rack

The rack face was made of expanded steel mesh which was cadmium plated, chromate conversion coated, and painted with MIL-P-23377 epoxy primer and MIL-C-81733 polyurethane topcoat. Specimens were insulated from the rack face by nylon washers and were fastened to the rack face with nylon bolts and nuts. MIL-A-46146 silicone rubber sealant was applied in the bolt holes of the specimens and under the bolt heads to prevent crevice corrosion. Specimens were exposed at a 45-degree angle to the vertical.

Weather Conditions

Weather reports were collected from hourly observations made by ship personnel on Form CNOC3140/8. From these reports, daily observations at 1200 hrs. and 2400 hrs. were recorded for atmospheric temperature, dew point, relative humidity, wind speed and sky cover. Table 1 shows the weekly averages for the atmospheric conditions. It is reported that temperatures at the carrier deck level can reach as high as 140°F(60°C), significantly greater than that of the ambient air. However, as seen in Table 1, ambient conditions were fairly uniform for most of the deployment. Atmospheric temperatures were greater than 68°F(20°C) most of the time and ranged typically from 72-85°F(22-29°C). The relative humidity varied typically from 62-84%. Conditions overall were not severe (as compared to the rainy season, for example) for a carrier environment.

Test MaterialsAluminum Alloy Control Specimens

One inch thick aluminum alloy 7075 T651 plate was machined into step specimens to expose the T/10 plane, with one tenth of the thickness removed, and the T/2 plane, with one half of the thickness removed. One step specimen was overaged to the T73 temper by heating for 24 hrs at 177°C (350°F), according to the Military Specification for Heat Treatment of Aluminum Alloys, MIL-H-6088F. The aluminum alloy exfoliation control specimens were prepared as follows:

DTIC QUALITY INSPECTED 8

19970604 052

1. Degrease
2. Etch in 5% NaOH at 80C (176°F), 3 min.
3. Rinse
4. Desmut in conc. HNO₃, 30 sec.
5. Rinse in deionized water
6. Dry in oil free air

Additional aluminum control specimens consisted of 6061 T6 and 2024 T6 flat panels

Cadmium Plated Steel Control Specimens

Steel (Type 4130) panels were bright cadmium electroplated with average thickness of 0.3 mils, 0.5 mils and 1 mil and used as control specimens to indicate severity of exposure. Severe rusting of only the .3 mil cadmium plated panel indicates a relatively mild exposure.

Test Specimens

The test rack prior to exposure is shown in Fig. 1. Positions on the rack are numbered from top to bottom and left to right and described in Table II. Included as test specimens were aluminum-lithium alloys (and Russian versions), high temperature and high strength aluminum alloys in various forms, aluminum metal matrix composites and aramid aluminum laminates, coated magnesium alloys and aluminum alloys with Unicoat primerless paint coatings.

Results and Discussion

General

All shipboard exposed specimens were discolored and covered with a thin, gray film upon return. The analysis of similar films from previous exposures indicated the film consisted primarily of MIL-L-23699 engine oil deposits with some sulfur (Ref.2). Appearance of the test specimens after shipboard exposure is shown in Figures 2,3,4 for the left, center and right sections of the rack respectively. Observations of the individual specimens after exposure are summarized in Table II.

Control Specimens

Cadmium plated steel, Figure 2, shows severe rusting of the 0.3 mil Cd plated steel (lower specimen, third row from left), whereas the 0.5 mil Cd plate (center) shows some surface darkening and general rusting and the 1.0 mil Cd plat (top) shows surface darkening with only very slight general corrosion. These control specimens are indications of a relatively mild exposure.

Aluminum Alloy Control Specimens

A small but noticeable amount of exfoliation occurred on the T/2 plane of the 7075 T651 step specimen. By comparison, the 7075 T76 step specimen showed only a small amount of pitting and general corrosion, as expected from a relatively mild exposure, demonstrating the improved exfoliation resistance of the overaged T76 condition. The remaining aluminum alloy control specimens in flat sheet configuration showed only some pitting and general corrosion.

Aluminum-Lithium Alloys

The melt spun Al-Li-Zr alloy 644 (position 20) step specimen appeared to be starting to exfoliate on the T/2 plane. The Russian alloy 1420 (position 35) showed a small amount of incipient exfoliation on both faces. The remaining Al-Li alloy step specimens (position 14, 36) showed only general corrosion with no exfoliation. The Al-Li sheet specimens (positions 12, 44, 46) showed only general corrosion and some pitting, similar to the other test and 7075 T6 control specimens.

Other Materials

The high temperature aluminum alloys, high strength aluminum, aluminum metal matrix composites and aramid aluminum (Arall) laminates sustained somewhat similar general corrosion. No increase in corrosion was noted at the edges of the unsealed Arall laminate. The exposure was mild and nothing other than general corrosion was observed (position 33-34). The significant result was no edge attack of the ARALL laminate.

Paints and Coatings

The Unicoat (primerless) painted specimens (positions 27-32) showed basically no effects of corrosion but some blisters occurred at the scribe marks of the coated 2024 T3 specimens (positions 25, 26). The Unicoat protected the base material from corrosion. Some surface darkening was observed. The appearance of the chromate corrosion coating, the nonchromate corrosion coating, and Alodine under Unicoat was basically similar. There was some surface darkening, and blisters at scribe marks. The Alodine showed some evidence that blisters may be forming. The over all result is that a more severe environment or longer deployment time may be required to reveal significant differences in behavior.

Conclusions

1. The improved exfoliation resistance of 7075 T7 (overaged) aluminum alloy over fully aged 7075 T6 was demonstrated, even after a relatively mild exposure.
2. Corrosion behavior of the aluminum lithium alloys was comparable to that of the other aluminum alloys in this exposure.
3. Unicoat (primerless) paint provided sufficient protection of the alloy surfaces, with blisters forming only at scribe marks through the coating.
4. Differences in corrosion behavior among the other alloys in this exposure were not discernible.

References

1. Joseph Kozol and Edwin Tankins, "Aircraft Carrier Exposure Tests of Cast Magnesium Alloys," NAWCADWAR-93015-60, March 1993.
2. J. J. Thompson, "Shipboard Exposure Testing of Aircraft Material, Aboard USS Constellation (Feb.-Sept. 1985)," NADC-87125-60, Sept. 1987.

Acknowledgments

Funding for this program was provided by the 6.2 Aircraft materials Block (NA2A). The authors wish to acknowledge Mr. Lee Biggs, Dr. Bart Boody and Dr. John DeLuccia for their assistance in evaluating the specimens after exposure testing.

Table I. Atmospheric Conditions - Weekly Averages.

Week	Atmos. Temp °C	Dew Pt. °C	Relative Humidity	Average Sky Cover	Average Wind Speed (Knots)
1	25	22.8	87	8	22
2	27.2	22.2	74	8	16
3	23.3	15.6	62	7	14
4	22.2	18.6	81	6.5	11
5	22.2	17.2	73	8	18
6	21	15	68.6	9	14
7	18.6	9.05	53.4	8.5	21
8	18.6	11.3	62.2	9	11
9	19.2	14.2	72.8	8	14
10	14.2	8.5	69	6	21
11	19.8	14.1	73	8	15
12	20.2	14.6	71.4	9	14
13	22.6	18	74.8	7	11
14	18.3	13.3	73	7.8	10
15	24	18.7	73	6.8	17
16	24.4	19.4	74	7.8	11
17	28.4	24.7	80	8.2	9
18	28.7	25.6	83.2	9	10
19	26.1	22.8	82	6.3	11
20	26.5	23.6	84	6	9
21	27.3	23.9	82	8	12
22	24.3	21.4	84	8	20

* On a scale of 1 to 10, 1 indicates clear skies and 9 indicates total cloud cover. 10 indicates thunderstorms.

TABLE II. SPECIMEN DESCRIPTION AND OBSERVATIONS

	Material Description	Designation	Configuration	Observation
1.	High Temp. Al alloy (Al-Fe-V-Si)	FVS 0812	Sheet	General corrosion, slight pitting not deep, slight surface discoloration.
2.	High Temp. Al alloy (Al-Fe-V-Si)	FVS 1212	Sheet	General corrosion, slight pitting not deep, slight surface discoloration.
3.	Aluminum Alloy	Control, 7075-T6	Sheet	Slight pitting not deep, and some general corrosion.
4.	Sealed Magnesium Alloy	WE-43		* Pitting of Al fitting, no galvanic corrosion discernible.
5.	Sealed Magnesium Alloy	QE-22		* No pitting, looks good.
6.	Unsealed Magnesium Alloy	QE-22		* Pitting of Al fitting with obvious galvanic corrosion at base of fastener.
7.	Cadmium Plated Steel (1 mil)	Control	Plate	Surface darkening, very slight general corrosion.
8.	Cadmium Plated Steel (0.5 mil)	Control	Plate	Surface darkening with edge corrosion.
9.	Cadmium Plated Steel (0.3 mil)	Control	Plate	Severe surface rusting.
10.	Aluminum Metal Matrix Composite	2124 T6, 15 vol SiC	Plate	Small amount of pitting, general corrosion and some surface discoloration.
11.	Aluminum Alloy	Control, 7075 T7351	Plate	Small amount of pitting, general corrosion and some surface discoloration.
12.	Al-Li Alloy (Russian)	1421	Welded sheet	Pitting and general corrosion.
13.	High Strength Aluminum Alloy	CW67T7	Plate	Small amount of pitting, some surface discoloration, mostly general corrosion.
14.	Aluminum-Lithium Alloy	2090T8	Step specimen	General discoloration, no exfoliation, general corrosion.
15.	High Strength Aluminum Alloy	CW67 T6	Plate	General discoloration, no exfoliation, general corrosion.
16.	Molybdate, Silane Coated Aluminum Alloy	2024 Coated	Plate	General discoloration, no exfoliation, general corrosion.

* Ref. 1.

TABLE II. SPECIMEN DESCRIPTION AND OBSERVATIONS (Continued)

	Material Description	Designation	Configuration	Observation
17.	High Strength Aluminum Alloy	CW67T7	Sheet	General discoloration, no exfoliation, general corrosion.
18.	Silane Coated Aluminium Alloy	2024 Coated	Plate	General corrosion, some pitting and surface discoloration.
19.	High Temperature Aluminum Alloy	CZ 42	Sheet	General corrosion, some pitting and surface discoloration.
20.	Melt spun Al-Li-Zr Alloy	644	Forged, extruded step specimen	General corrosion, some pitting and surface discoloration, exfoliation appears to be just starting at T/2.
21.	Aluminum Alloy	Control, 6061T6	Plate	General corrosion, and some pitting.
22.	Aluminum Alloy	Control, 2024T6	Plate	General corrosion, and some pitting.
23.	Aluminum Alloy	Control, 7075T76	Step specimen	Pitting and general corrosion.
24.	Aluminum Alloy	Control, 7075T6	Step specimen	Exfoliation starting on mid plane. No evidence on top plane.
25.	Chromate Corrosion Coating, Unicoat Variation	2024T3	Plate	Blisters at scribe marks. Paint Surface looks good.
26.	Chromate Corrosion Coating, Unicoat Variation	2024T3	Plate	Blisters at scribe marks. Paint Surface looks good.
27.	Non-Chromate Corrosion Coating, Unicoat Paint	2024T3	Plate	No corrosion, some surface darkening.
28.	Non-Chromate Corrosion Coating, Unicoat Paint	7075T6	Plate	No corrosion, some surface darkening.
29.	Non-Chromate Corrosion Coating, Unicoat Paint	6061T6	Plate	No corrosion, some surface darkening, blisters may be forming.
30.	Alodine, Unicoat Paint	2024T3	Plate	Blisters may be forming.

TABLE II. SPECIMEN DESCRIPTION AND OBSERVATIONS (Continued)

	Material Description	Designation	Configuration	Observation
31.	Alodine, Unicoat Paint	7075T76	Plate	No corrosion, some surface darkening.
32.	Alodine, Unicoat Paint	6061T6	Plate	No corrosion, some surface darkening.
33.	Aramid Aluminum Laminate	Arall 5/4	Unsealed edges	General Corrosion - No discernible increase at laminated edges.
34.	Aramid Aluminum Laminate	Arall 5/4	Sealed edges	General Corrosion.
35.	Al-Li Alloy (Russian)	1420	Step specimen	Incipient exfoliation on both faces.
36.	Al-Li Mechanically Alloyed	Inco 905XL	Forging Step Specimen	No exfoliation, some pitting and general corrosion.
37.	High Strength Aluminum Alloy	CW67TX1	Forging	Some pitting and general corrosion.
38.	Aluminum Metal Matrix Composite	2124 T6, 15 vol SiC	Sheet	Some pitting and general corrosion.
39.	High Temp. Aluminum Alloy	Al-12.6Mn, 4.8Si, 0.2 Fe	Extrusion	General corrosion, similar to #1 except darker discoloration.
40.	High Temp. Al Alloy (Al-Fe-V-Si)	FVS 1212	Extrusion	General corrosion, some pitting and surface discoloration.
41.	Unsealed Magnesium Alloy	QE-22		* Pitting of Al fitting, galvanic corrosion; coating at scribe in base material severely corroded.
42.	Sealed Magnesium Alloy	QE-22		* Severe corrosion at scribe, not as bad as #41.
43.	Sealed Magnesium Alloy	WE-43		* Tiny amount of corrosion at scribe, no galvanic effects noted.
44.	Al-Li-Mg Alloy (Russian)	1420w	Sheet	General corrosion, some surface discoloration.
45.	High Temp Al Alloy (Al-Fe-V-Si)	FVS 0812	Sheet	Incipient pits, slightly more general corrosion than #1.
46.	Al-Li-Mg Alloy (Russian)	1421w	Sheet	Some pits, general corrosion.

* Ref. 1.




Figure 1. Test Specimens Prior To Shipboard Exposure.




Figure 2. Left Section Of Rack After Exposure.




Figure 3. Center Section Of Rack After Exposure.




Figure 4. Right Section Of Rack After Exposure.

DISTRIBUTION LIST (continued)
Report No. NAWCADWAR-94019-60

No. of Copies

Center for Naval Analysis 1
 4401 Fort Avenue
 P.O. Box 16268
 Alexandria, VA 22302

U 9500006

Naval Air Warfare Center 2
 Lakehurst, NJ 08733
 (1 for K. Megerle, S
 (1 for G. Fisher, SE

NAWCADWAR
 NAWCADWAR-94019-60

Metals Information Analysis 1
 Purdue University
 Lafayette, IN

Date Due

U 9500006

Office of Naval Research 1
 Materials Division, Engineering
 800 N. Quincy Street
 Arlington, VA 22217-5001
 (1 for G. Yoder, Code

NAWCADWAR
 NAWCADWAR-94019-60

DATE DUE	BORROWER'S NAME	ROOM NUMBER

NAVAL GENERAL LIBRARIES
Chief of Naval Education
and Training

DISTRIBUTION LIST

Report No. NAWCADWAR-94019-60

	No. of Copies
Naval Air Systems Command	4
Jefferson Plaza One	
Washington, DC 20361-5300	
(1 for S. Bettadapur (AIR-5304D))	
(1 for J. Collins (AIR-5304))	
(1 for J. Thompson (AIR-5304C))	
(1 for W. Koegel (AIR-5304D))	
 NADEP Cherry Point	 2
Cherry Point, NC 28533-5030	
(1 for B. Helms (Code-354))	
(1 for Code 340)	
 NADEP Alameda	 1
Alameda, CA 94501	
(1 for Code 340)	
 NADEP Pensacola	 1
Pensacola, FL 32508-5300	
(1 for O. Hayes (Code 340))	
 NADEP Norfolk	 1
Norfolk, VA 23511	
(1 for Code 340)	
 NADEP Jacksonville	 1
Jacksonville, FL 32212	
(1 for Code 340)	
 NADEP North Island	 1
San Diego, CA 92135	
(1 for Code 340)	
 Defense Technical Information Center	 2
Bldg. 5, Cameron Station	
Alexandria, VA 22314	
 Naval Air Warfare Center Aircraft Division	 12
Warminster, PA 18974-0591	
Attention:	
(10 for J. Kozol (Code 6063))	
(2 for Technical Library (Code 0471))	

U950006